



Town of Barre

Board of Health
40 West Street - Box 431
Henry Woods Building
Barre, Massachusetts 01005

E-mail – boardofhealth@townofbarre.com
Tel. 978-355-2504 x 117 Fax 978-355-5009



MOLD

Owners

If you are the owner or landlord of a property there are certain steps you can take in order to prevent mold from becoming a problem.

The **first step** is to have an ongoing relationship with your tenants. Maintain good communications and be proactive in responding to any concerns. Provide the tenants with clear guidelines for reporting problems and seeking solutions.

The **second step** is to understand your responsibilities in preventing mold. Please refer to Massachusetts DPH: 105 CMR 410.000 State Sanitary Code Chapter II. Minimum Standards of Fitness for Human Habitation, Section 410.500, for complete regulations.

The following is a list of potential problem areas that when addressed will help to minimize mold growth:

1. Inspect all appliances and faucets regularly including; drip pans, cooling coils under or behind refrigerators, and air filters.
2. Complete repairs to roofs, gutters, windows and foundation cracks in a timely manner.
3. Do not install carpet in bathrooms.
4. Do not install carpet directly on poorly ventilated concrete floors.
5. Install exhaust fans in bathrooms and kitchens.
6. Ventilate attic and crawl spaces. (Keep relative humidity below 50%)
7. Use dehumidifiers in basements. (Be sure to follow instructions on proper use and maintenance)
8. Vent clothes dryers to the outside.
9. After flooding, all carpets should be thoroughly cleaned and dried or replaced.

For more information please visit any of the websites listed below

1. The Us Environmental Protection Agencies website at:
<http://www.epa.gov/mold/moldguide.html> or
http://www.epa.gov/iaq/largebldgs/pdf_files/appenc.pdf
2. The Centers for Disease Control (CDC) website:
<http://www.cdc.gov/mold/>